ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
DASARAHALLI

Ward No.
15

Ward Name
T Dasarahalli

Street ID
W0057, W0024, W0080, W0081, W0061, W0012, W0048, W

Street Name
NA, 14th Crs, Om Shakthi Lyt 7th Crs

Significant Landmark
Ganesha Saw Mill

Segment No.
15/C-W0057/S062339

Total Length (m)
812.87

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	24.01	77.511016	13.044979	77.510804	13.045041	Ganesha Saw Mill road	Deadend
2	140.29	77.511067	13.044971	77.512306	13.044608	Ganesha Saw Mill road	Kannada Kasthuri Road (W0081)
3	143.57	77.510911	13.044422	77.512201	13.044132	Ganesha Saw Mill road	Kannada Kasthuri Road (W0081)
4	109.96	77.511684	13.047526	77.511960	13.048483	1st Main Road	Ward Boundary
5	395.04	77.510753	13.044020	77.511660	13.047477	NH4	1st Main Road

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements and Re-Asphalting to Ganesha Saw Mill road and surrounding roads in Dasarahalli Ward No.15

Sanctioned Estimated Amount (Rs.)
4000000

Sanctioned Year
2020

Year
2020 - 2021

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details

Job No. / Work Code
015-20-000107

Work Order No.
EE/DD/WO/03/2022-23

Work Order Date
20/04/2022

Period of Extention

Defect Liability Period From
02/06/2022

Defect Liability Period To
01/06/2023

Multiple road involved with the same Job No/ Work Code #
No

Contractor Details

Name of Contractor

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)

Zone: DASARAHALLI **Ward No:** 15 **Ward Name:** T Dasarahalli **Street ID:** W0057, W0024, W0080, W0081,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ. ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

Scanned with CamScanner

d Inspection Details

umber of Trees

Any Other Information

Name

Archana

Date of Inspection

02/06/2022

Remarks

Category	Image	Photo Remark
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Segment End		Location was not determined.
Segment End		Location was not determined.
Segment Start		Location was not determined.
Segment Start		Location was not determined.

Zone: DASARAHALLI **Ward No:** 15 **Ward Name:** T Dasarahalli **Street ID:** W0057, W0024, W0080, W0081,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ. ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

Scanned with CamScanner

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	CE DAS	02/06/2022	02/07/2022	APPROVED
EE	EE DAS	02/06/2022	02/07/2022	COMPLETED
AEE	Ranganath B R	02/06/2022	02/07/2022	Completed
AE	Archana	02/06/2022	02/07/2022	Completed
AE	Archana	02/06/2022	02/07/2022	Completed

Approved.15

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

Scanned with CamScanner